

IDWAL

Report commissioned by:

GSE TEAM

Organisation:

Guangzhou Shipping Exchange Co., Ltd



PRE-PURCHASE
INSPECTION

SHANDONG FU ZE

IMO Number: 9734721

INSPECTED AT SAO FRANCISCO DO SUL BRAZIL
1st SEPTEMBER 2023



REPORT TERMS OF USE

This report is intended for the sole use of **GSE TEAM** and is designed to offer a condition evaluation of the subject vessel, as found on the day of the survey and in the opinion of the surveyor concerned. The report is subject to any access restrictions as described herein, and subject always to the level of cooperation afforded to the surveyor during the inspection itself. All details are given in good faith, and without guarantee.

This report has been prepared and issued by Idwal Marine Services Ltd to its Customer, **GSE TEAM of Guangzhou Shipping Exchange Co., Ltd**, in accordance with, and subject to, the General Terms and Conditions of Idwal Marine Services Ltd, a copy of which can be obtained at www.idwalmarine.com/terms-conditions. Attention is particularly drawn to restrictions on reproduction and disclosure of, and limits on reliance on, this Report as more fully set out therein.

To access all documents related to this report, and verify the authenticity of its contents, please view the full version available here:

customer.idwalmarine.com/22-1435

Pre-sale report reference:	22/1435
Report commissioned for:	GSE TEAM
Organisation:	Guangzhou Shipping Exchange Co., Ltd
PDF generated for:	zhouruoyu@gzport.com
Time & date:	23:35 (UTC) on 7th September 2023



At Idwal, we are proud to run a carbon neutral business and provide the industry's first carbon neutral inspection service. Idwal has been carbon neutral since 2021 and has achieved PAS 2060 certification from Carbon Footprint Ltd.



Carbon
Neutral
Organisation
PAS 2060



CONTENTS

INSPECTION SUMMARY	3
COMPARE YOUR IDWAL GRADE	5
KEY NOTABLE ITEMS	6
DECARBONISATION SUMMARY	8
GRADING DATA	9
DESIGN AND CONSTRUCTION	10
HULL	11
MOORING DECKS	12
WEATHER DECKS AND FITTINGS	13
BALLAST TANKS AND SYSTEMS	14
ACCOMMODATION	15
BRIDGE AND NAVIGATION EQUIPMENT	17
ENGINE ROOM AND MACHINERY	18
FIRE FIGHTING EQUIPMENT AND SYSTEMS	23
LIFESAVING APPLIANCES	24
SAFE WORKING ENVIRONMENT	25
POLLUTION CONTROL	26
ONBOARD MANAGEMENT	28
VESSEL CAPABILITIES AND CARGO SYSTEMS	29

ADDITIONAL DOCUMENTS



Vessel documents



Vessel photos



INSPECTION SUMMARY

78

IDWAL
GRADESao
Francisco
Do Sul,
Brazil

01 Sep 2023

Status:
Loading17.5 Hours
AboardMajority of
documents
provided

VESSEL PARTICULARS

Ship Name	SHANDONG FU ZE
Previous Name	N/A
IMO Number	9734721
Port of Registry	Hong Kong
Ship Type	Bulk Carrier
Flag	China
Classification Society	China Classification Society 2017-03
Registered Owner	Sea 256 Leasing Co Ltd
Technical Manager	Thome Shipping Pte Ltd
Shipbuilder	Jiangsu Jinling Ships Co Ltd
Delivery Date	15/03/2017
Dead Weight	81781.00 MT
Gross Tonnage	44120.00 MT
Net Tonnage	27591.00 MT
Length Overall	229.00 m
Breadth	32.26 m
Depth	20.05 m
Summer Draught	14.45 m
Lightweight	13517.00 MT

The SHANDONG FU ZE is an 81,781 DWT, 44,120 Gross Tonnage, China flagged, gearless Bulk Carrier vessel built to a good standard by Jiangsu Jinling Ships Co Ltd, in China under China Classification Society supervision and was delivered on the 15th March 2017. The vessel remains classed with the China Classification Society.

A Pre-purchase Inspection of the vessel was conducted from the 31st of August 2023 to the 1st of September 2023 in Sao Francisco Do Sul, Brazil by Idwal under instruction from Guangzhou Shipping Exchange Co., Ltd.

Good cooperation was provided by the ship's crew with access provided to the cargo holds. The ballast tanks were not able to be inspected due to the ballast operation being in progress however, previous inspection photos were shared for review with the assessment of the condition based on these. The vessel was alongside, loading at the time of inspection.

The vessel was found to be in good overall condition with an Idwal Grade above the average for vessels of a similar age, type and size but with a few notable items found during the inspection. These are reported specifically in the notable items section of this report.


The onboard management was found to be good with the Safety Management system found to be well implemented and the vessel generally maintained. The vessel was found to provide a safe working environment. The Port State Control (PSC) history was found to be very good with 0 deficiencies and 0 detentions in the 6 inspections conducted in the past three years.

The vessel was delivered in March 2017 with an Energy Efficiency Design Index (EEDI) of 3.69 however, as per the data provided during the inspection, the Required EEXI for the vessel is now 3.49 which indicates a reduction in the main engine MCR may be required to meet compliance.

COMPARE YOUR IDWAL GRADE

This section of the report allows you to compare your ship's grade with similar ships.

Your Idwal Grade vs other Panamax Bulk Carrier vessels




This graph shows the distribution of Idwal Grades against your ship's sector.

KEY

- Your Idwal Grade ———
- Average Idwal Grade - - - -
- Grade range
- ≥ 90 (green)
- 70 - 89 (yellow-green)
- 50 - 69 (orange)
- 30 - 49 (red)

Your Idwal Grade vs other Panamax Bulk Carrier vessels, age 5-10 years



This graph shows your ship's Idwal Grade compared against other ships inspected in the same sector, within a similar age range, and how it compares against the average Idwal Grade for the sector.

KEY

- Your Idwal grade ●
- Average Idwal grade - - - -
- All sector ships ●
- Age comparable ships ●

The ship's grade may appear different when compared with the average of the two graphs. This is as a result of the second graph comparing a smaller and more focused sample of ships.

For a more in-depth analysis of where your vessel compares amongst its peers, please contact your Idwal sales rep.

KEY NOTABLE ITEMS

Description	Action / Timeline	Estimated Cost [USD]
 Cargo Hold No.1 vertical ladder was observed with a slight bent, Hold No.2 pipe protection bars were observed with a slight bent, Hold No.5 platform from the vertical leader was observed with a slight bent and Hold No.5 protection bars for pipes were seen bent at certain places.	To plan and repair as considered necessary.	\$1000 - \$5000
 It was noted that the fuel pump overhaul on auxiliary engine number 3 was overdue.	To be further investigated and any required overhaul carried out as soon as practical.	\$1000 - \$5000
 It was noted that the main engine main start ball valve overhaul was overdue.	To be further investigated and any required overhaul carried out as soon as practical.	\$1000 - \$5000
 The vessel was seen to be lacking critical spares with numerous items noted to be missing including emergency fire pump automatic deaerator valve and emergency generator starting motor/starter.	Ensure the vessel has adequate spares as recommended by the ship manager Safety Management System (SMS).	\$1000 - \$5000
 The main engine was seen with oil stains and minor leaks near cylinder heads and near fuel pumps at the forward end of the main engine.	Rectify the leaks as soon as reasonably possible.	\$1000 - \$5000
 Engine room pipework was found to have leaks around pipework related to hand-operated hydraulic pumps on engine room bottom plates	Rectify minor leaks, and consideration should be given to renewing deteriorated pipework.	\$1000 - \$5000
 Icing and a collection tray were observed below the evaporator unit in one of the provision stores.	To investigate and take appropriate action.	<\$1000
 Oil leakage was observed near Auxiliary engine No.1 Fuel filters	To investigate and repair as required.	<\$1000
 Black stained marks were observed on the main engine exhaust casing.	To investigate and take appropriate action.	<\$1000
 According to the running hours data provided Auxiliary Engine No.1 was reported to have only 47 hours left for its major overhaul of 12,000 hours.	For information.	\$0

	It was reported that an IMO approved BWTS is installed with no documentation provided onboard to verify it's USCG compliance	This is recommended to be further investigated.	\$0
	The vessel is reportedly fitted with free to access limited use Wi-Fi system		\$0
	The vessel is fitted with an air seal on the stern tube and is therefore Vessel General Permit (VGP) compliant in this regard.		\$0

Please note, all costs are estimations only, based on industry averages, and may vary depending on locations and scopes of work. These costs are provided to assist the reader to consider the potential Capex or Opex impact of the related Notable Item and should not be used for budgeting purposes without further internal assessment of their accuracy.

DECARBONISATION SUMMARY

The vessel was delivered in March 2017 with an Energy Efficiency Design Index (EEDI) of 3.69 however, as per the data provided during the inspection, the Required EEXI for the vessel is now 3.49 which indicates a reduction in the main engine MCR may be required to meet compliance. For more information about technologies to reduce a vessel's EEXI, the creation of the EEXI technical file or operational measures to reduce a vessel's Attained CII, please contact your Idwal sales representative.

EEXI

Required EEXI

3.49

gCO₂/t.nm

Attained EEDI/EEXI

3.69

gCO₂/t.nm

Vessel does not meet the EEDI/EEXI requirement and requires additional retrofitting of technologies

GRADING DATA



The Idwal Grade® is an industry recognised measure of asset integrity. Using proprietary algorithms, the Idwal Grade is programmatically calculated from over 500 individual data points, captured during a rigorous and standardised inspection process. Our data-driven methodology ensures that our reports are consistent, accurate and free from bias.

SUB GRADES

The methodology used to calculate the Idwal Grade® is also applied to the grading of the different vessel areas and categories. Two key areas are the overall vessel condition and vessel management:



The following are grades representing individual areas of interest of the vessel:



DESIGN AND CONSTRUCTION

80

The construction and design were found to be good overall, with the vessel built to IACS standards and Rules in China by Jiangsu Jinling Ships Co Ltd with the keel laid on 18 November 2015. The vessel is a Bulk Carrier, with 7 holds, driven by a fixed pitch, direct drive propeller. The Main Engine is a NOx Tier 1, MAN B&W; the vessel has 3 Auxiliary Engines and no shaft generator. While crew reported the engines to be NOx Tier 2 no documentation was shared for review to verify with it

recommended this is further investigated and verified. The vessel is subject to the Enhanced Survey Program (ESP) and holds a Class notation for In Water Surveys. No Cargo Lifting Appliances are fitted and the vessel does not carry grabs. The engine room is fitted with an incinerator sludge burning system and UMS capabilities. It was also reported that an Engine Power Limiter (EPL) was fitted as detailed in the relevant Class Memo.

HULL

80

The hull was seen to be in a good overall condition, with the hull able to be inspected from the port side only. The vessel was found to be free of both major and minor structural defects. The hull plating had only minor localized surface corrosion, up to approximately 5% of the visible surface area. The coating damage and corrosion were primarily situated along the

shell plate, particularly on the aft part, where the coating had been abraded due to routine contacts. Hull markings were well painted and legible with no marine fouling observed. The vessel's last out of water bottom survey was credited on 17-Jan-22, with the vessel's next out of water bottom survey due by 14-Mar-27.

MOORING DECKS

80

The Mooring decks were seen to be in a good condition overall with the decks found to be free of structural defects and had only minor localised spot corrosion, up to approximately 5% of the mooring deck plating total surface area, mainly located on the weld seams on fore and aft mooring deck plating. Cargo residues were observed on the mooring deck plating. Deck fittings were found to be in a good condition with fair leads and mooring rollers free to turn when tested. All Hydraulic windlass and winches were reported to be fully operational and free from hydraulic leakage as observed. Mooring machinery was in generally good condition with the band brake linings seen to have adequate remaining thickness. Visible anchor chains

and mooring ropes were in a good overall condition. Mooring practices were seen to be fair, due to certain mooring drums having overlapping turns on split drums and certain mooring drums were seen with inadequate turns on split drums. Snap-back zone warnings were seen to be posted at the entrances to mooring areas as per industry best practice. The Bosun's store was in a good overall condition with no issues to the structure, coatings or housekeeping observed. The bitter end release arrangements were seen to be clear and unobstructed and the emergency towing booklet was seen to be available near the Foc'sle.

WEATHER DECKS AND FITTINGS

80

The Weather Decks and Fittings were deemed to be in good condition overall, with the decks found to be free of structural defects and had only minor localised spot corrosion, expected to not be more than 5% of the main deck plating total surface area, mainly located on cross decks and port side near number 1 hatch cover. Scattered residues of the current cargo were

noted throughout the weather decks. Deck fittings were found to be in a good condition with pipework and fittings free of leakages and deck mooring machinery was in good condition. The accommodation ladders and gangways were in a good overall condition, with no notable defects found, as were provisions lifting appliances.

BALLAST TANKS AND SYSTEMS

80

From the information provided the ballast tanks and systems were deemed to be in a good overall condition. Ballast tanks were not able to be entered due to ongoing ballasting operations. However, photographs of previous tank entries, reportedly taken on 18-Dec-22, were provided for review. From the photographs provided, it was reported that the ballast tanks were generally free of significant structural defects and were stated to have only minor localised spot corrosion, up to approximately 5% of the ballast tanks total surface area,

mainly located on the edge of structural members, frames and plating. Ballast tank fittings such as ladders and pipework were reported to be in a good overall condition with Anodes reported to be depleted by up to 10%. Tanks were reported to have no mud/sediment accumulation and were stated to be free of any signs of staining from sewage or marine fouling. Ballast control systems such as valves and gauges were reported to be fully operational and all ballast pumps were in good working order and in good visual condition.

ACCOMMODATION

80

The accommodation areas were seen to be in a good condition overall with floor and wall coverings found to be in good condition and upholstery and furniture found to be free from deterioration and defects. The levels of housekeeping and cleanliness were found to be good with levels of hygiene also seen to be good in the sanitary facilities. The hospital was seen to be well equipped and ready for use with the drugs seen to be controlled and secured and with the associated drugs log kept up to date. The accommodation was found to be outfitted to an average quality. The Air Handling Unit (AHU) was found to be maintaining a comfortable temperature and was seen to be in good condition with no defects. The galley equipment was deemed to be in a good overall condition with all equipment reportedly in good working order. The galley was found to be in a clean condition with the galley hoods also found to be kept clean. The vessel's walk-in cold rooms were found to be clean and hygienic with temperatures at the required levels. Provision room components were seen to be generally free of frosting and deterioration. However, icing and collection tray were observed below the evaporator unit in one of the provision stores, requiring further investigation and appropriate action. The external superstructure was found to be free of structural defects and had only minor localised spot corrosion, not more than 5% of the surface area, mainly located on porthole edges and weld seams. The external superstructure fittings were seen to be in a good overall condition with all external

accommodation doors in good working order and properly closing. The vessel's Crew Welfare was found to be good overall. The average contract length was reported to be 7 Months for the vessel's Officers and 9 Months for the vessel's crew, with it noted that a crew suggestion policy was seen to be in place. The vessel was reported to have free to access and limited use Wi-Fi onboard which was available to all crew. It was reported that the approximate average internet speed was average, indicating the crew were able to access social media apps and websites with ease. The vessel was seen to have various pieces of public recreational equipment that the crew could access, including Free Weights, Fixed weight machine, Treadmill, Cycling Machine, Table Tennis, Television, Games console, Karaoke, Entertainment Library - Books, DVDs, Games, etc., Musical Instruments, Barbecue, Public Computer, En-suite facilities for all crew members. These equipment were found to be in a good overall condition. As per crew reports access is provided to catering facilities at all times, with it also reported that crew were given additional time and resources to celebrate religious and cultural events. It was seen that various facilities were provided in all crew cabins, including Sofa, Desk, and Ample storage. It was also stated that the crew had access to a minimally-stocked bond store. It was stated that the vessel has onboard training facilities as provided by Videotel and Seagull, with it also noted as per crew reports additional periods of rest were given throughout the working week.

NOTABLE ITEMS

Description	Estimated Cost [USD]
-------------	----------------------



Issue: Icing and a collection tray were observed below the evaporator unit in one of the provision stores.

<\$1000

Corrective Action: To investigate and take appropriate action.



Description

Estimated
Cost [USD]



Issue: The vessel is reportedly fitted with free to access limited use Wi-Fi system

\$0

BRIDGE AND NAVIGATION EQUIPMENT

80

The Bridge and navigation equipment were found to be in a good condition overall with housekeeping found to be good and with all bridge equipment reported to be fully operational. The vessel's VDR was found to be free from any unanticipated alarms with collection instructions posted nearby and with the Bridge Navigation Watch Alarm System (BNWAS) reported to be fully operational. The vessel's primary means of navigation, as listed on form E of the safety equipment certificate is a dual ECDIS system which were found to be up to date. An in-date compass deviation card was seen to be posted near the helm and the compass deviation log was well-maintained and without any major deviations. The vessel is licensed to cover GMDSS sea areas A1, A2, and A3

and has a valid shore-servicing agreement in place. The radio batteries were seen to be well maintained and in good condition and the EPIRB, SART and VHF handheld batteries were all in date as required. Berth to berth passage plans were seen on board and were signed by all navigating officers with nautical publications provided in Paper and Electronic format. Master's standing and night orders were found to be signed by all navigating officers with the bridge log book correctly filled in and the GMDSS logbook was also up to date and correctly filled in. The Monkey Island was found to be in a good overall condition with the mast, aerials and antennas seen to be satisfactory and free of defects.

ENGINE ROOM AND MACHINERY

60

The Engine room and machinery were found to be in a fair overall condition due to oil stains and minor leaks observed near cylinder heads and near fuel pumps at the forward end of the main engine and oil leakage observed near Auxiliary engine No.1 Fuel filters. There were no significant defects reported or observed and the engine room was generally found to be clean. During the inspection, the Auxiliary Engines, purifiers, pumps and air compressors were seen running. Bilges and tank tops were generally free of oil or water. Pipework was seen with evidence of hydraulic oil leakage around pipework related to hand-operated hydraulic pumps on engine room bottom plates. Some pipework lagging has areas of deterioration and staining. Housekeeping was seen to be to a good overall standard with the vessel lacking critical spares as recommended by the ship manager's Safety Management System (SMS) with numerous items noted to be missing including emergency fire pump automatic deaerator valve and emergency generator starting motor/starter. A review of the latest lube oil analysis reports provided showed no areas of concern. The NOx Technical file was up to date and last updated on 24-Aug-23. The Main Engine was reported to be fully operational but was seen to be in a fair overall condition due to oil stains and minor leaks observed on cylinder heads and near fuel pumps at the forward end of the main engine. Black stain marks were also observed on the main engine exhaust casing which require to be further investigated. A review of the latest Main Engine performance report provided showed no areas of concern. A review of the latest engine running hours showed that the Bearings

and Cylinder Liners overhaul schedules are subject to Condition Based Monitoring (CBM) and therefore no dedicated overhaul intervals are provided and Cylinder heads and Pistons overhauls were within the service hours. It was however noted that the main start ball valve overhaul was overdue. Propulsion systems, such as shafts, gearing and bearings were in good working order with no defects reported or sighted. The 3 Auxiliary Engines were reported to be fully operational. Oil leakage was observed near the Auxiliary engine No.1 Fuel filters. A review of the latest Auxiliary engines performance report provided showed no areas of concern. According to the running hours data provided Auxiliary Engine No.1 was reported to have only 47 hours left for its major overhaul of 12,000 hours. It was also noted that the fuel pump overhaul on auxiliary engine number 3 was overdue. The vessel's steam boiler was found to be fully operational and in good condition. The boiler safety valves were seen to be satisfactory and free of tampering. All Auxiliary equipment was found to be fully operational and in good condition. The steering gear was seen in good working order, free of leakage with emergency steering instructions seen to be posted nearby. The machinery spaces are operated in Unmanned mode and the alarm and control system was seen to be free of any serious alarms. Electrical distribution systems including the main switchboard were in good working order and switchboard insulation readings were adequate. The emergency generator was tested during the inspection and found to be in good working order and in a good overall condition.

NOTABLE ITEMS

Description

Estimated
Cost [USD]



Issue: It was noted that the fuel pump overhaul on auxiliary engine number 3 was overdue.

Corrective Action: To be further investigated and any required overhaul carried out as soon as practical.

\$1000 -
\$5000

Description

Estimated
Cost [USD]



Issue: It was noted that the main engine main start ball valve overhaul was overdue.

Corrective Action: To be further investigated and any required overhaul carried out as soon as practical.

\$1000 -
\$5000

Description

Estimated
Cost
[USD]



Issue: The vessel was seen to be lacking critical spares with numerous items noted to be missing including emergency fire pump automatic deaerator valve and emergency generator starting motor/starter.

Corrective Action: Ensure the vessel has adequate spares as recommended by the ship manager Safety Management System (SMS).

\$1000 -
\$5000

Description

Estimated
Cost
[USD]



Issue: The main engine was seen with oil stains and minor leaks near cylinder heads and near fuel pumps at the forward end of the main engine.

\$1000 -
\$5000

Corrective Action: Rectify the leaks as soon as reasonably possible.



Description

Estimated
Cost
[USD]



Issue: Engine room pipework was found to have leaks around pipework related to hand-operated hydraulic pumps on engine room bottom plates

\$1000 -
\$5000

Corrective Action: Rectify minor leaks, and consideration should be given to renewing deteriorated pipework.



Description

Estimated
Cost [USD]



Issue: Oil leakage was observed near Auxiliary engine No.1 Fuel filters

Corrective Action: To investigate and repair as required.

<\$1000



Description

Estimated
Cost [USD]



Issue: Black stained marks were observed on the main engine exhaust casing.

Corrective Action: To investigate and take appropriate action.

<\$1000



Description

Estimated
Cost
[USD]



Issue: According to the running hours data provided Auxiliary Engine No.1 was reported to have only 47 hours left for its major overhaul of 12,000 hours.

Corrective Action: For information.

\$0

FIRE FIGHTING EQUIPMENT AND SYSTEMS

80

Fire Fighting Equipment and Systems were found to be in a good condition overall and generally free of fire hazards with all firefighting equipment seen to be regularly serviced and inspected. The fire detection and alarm system was found to be fully operational and was free of signs of tampering and alarms. The vessel is fitted with Water Spray and CO2 fixed firefighting in the engine room, and CO2 for the cargo areas. Fixed firefighting systems were all reported to be in good working condition with operating instructions clearly posted. The main and emergency fire pumps were reportedly fully operational and both were found to be in a good condition, free of leakages. A fire pump was tested

during the inspection and was found to deliver adequate pressure. The fire main and ancillaries such as hydrants and valves were in good overall condition, free of defects. Fire extinguishers were all in good condition and all portable equipment were positioned in accordance with the fire plan. Firefighting outfits and associated equipment were all in good condition with BA equipment found fully charged and ready for use. Remote shutdown emergency devices such as quick closing valves, machinery stops and ventilation dampers were deemed to be in a good overall condition with no defective shutdown equipment. The fire doors were found to be in good condition, closing effectively.

LIFESAVING APPLIANCES

80

Lifesaving appliances were seen to be in a good overall condition with all equipment regularly serviced and inspected as required. The vessel is fitted with a free-fall lifeboat, which was seen to be in good overall condition externally and internally. The lifeboat engine was tested during the inspection and found to be in good working order. The vessel's rescue boat was found to be in a good overall condition and ready for immediate use. The vessel is equipped with 5 life rafts, which were found to be in good condition with Hydrostatic Release Units (HRUs) in date and correctly rigged. Davits and lowering

arrangements were found to be in good condition overall with evidence of regular maintenance, servicing and inspection sighted and evident. Ancillary lifesaving equipment such as lifejackets, immersion suits EEBD etc. were found to be in good condition and ready for immediate use with man overboard smoke and light signals seen to be in date. Embarkation ladders were found to be in a good, well maintained condition with the pyrotechnics and line throwing apparatus found to be stored appropriately and within their expiry dates.

SAFE WORKING ENVIRONMENT

80

Safe working was deemed to be good overall with no unsafe practices observed during the inspection and the vessel presenting a generally safe working environment. Hazards were seen to be clearly marked and external walkways were adequately coated with non-slip paint and free of trip hazards. Portable gas detection meters were provided and stated to be calibrated. however not all crew were seen to be wearing the required PPE when on the open decks. Hazardous substances were seen to be generally safely managed with appropriate

Material Safety Data Sheets provided. Risk Assessments (RA) were seen to be up to date and satisfactory with enclosed space entry procedures followed and an effective Permit To Work (PTW) system in place. Main and emergency exits were clearly identified and unobstructed with all IMO signage seen to be satisfactory. Pilot ladders and boarding arrangements were seen to be in a good, safe condition. Regular drills were conducted on board with the last drill conducted on 13-Aug-23, which was an Abandon ship, Fire fighting, Oil spill and Rescue boat drill.

POLLUTION CONTROL

90

Pollution control was deemed to be good to very good overall and generally found to be well implemented on board with the vessel free of pollution hazards. The vessel holds a Class-approved Inventory of Hazardous Materials, which is required for entry into EU ports. The vessel's Oily Water Separator (OWS) was found to be fully operational and in good overall condition, with no obvious defects. The OWS was simulation tested during the inspection and the 15ppm Oil Content Meter (OCM) was seen to be calibrated. The bilge overboard was seen to be sealed and locked against unauthorised opening and the oily water treatment system as a whole was seen to be free from signs of tampering or unauthorised modification. The SOPEP locker was found to be well stocked with SOPEP equipment in good condition and an accurate list of equipment was posted nearby. The Oil Record Book (ORB) was seen to be well-maintained and up-to-date, with the last entry on the 29-Aug-23. It was reported that an IMO-approved Ballast Water Treatment System (BWTS) is fitted onboard with no documentation

provided to verify its USCG compliance which was found to be fully operational and in good overall condition. The vessel's ballast record book was seen to be up to date and correctly filled in. The vessel is fitted with an air seal on the stern tube and is therefore Vessel General Permit (VGP) compliant in this regard. The vessel's sewage treatment plant was found to be fully operational and in good overall condition, with no obvious defects. Garbage segregation was found to be good, with adequate, labelled containers and garbage seen to be well sorted and containers seen to be made of approved non-combustible materials. The Garbage Record Book (GRB) was seen to be well-maintained and up-to-date, with the last entry on 17-Aug-23. The Emission Control Area (ECA) change-over logbook was reviewed and found to be satisfactory with the date of last entry on 21-Nov-22. The vessel's incinerator was found to be fully operational and in good overall condition, with no obvious defects. The vessel complies with IMO 2020 regulations by employing the use of Very Low Sulphur fuel oils (VLSFO) with a sulphur content of less than 0.5%.

NOTABLE ITEMS

Description	Estimated Cost [USD]
<p>Issue: It was reported that an IMO approved BWTS is installed with no documentation provided onboard to verify it's USCG compliance</p> <p>Corrective Action: This is recommended to be further investigated.</p>	\$0

Description	Estimated Cost [USD]
-------------	----------------------------



Issue: The vessel is fitted with an air seal on the stem tube and is therefore Vessel General Permit (VGP) compliant in this regard.

\$0

ONBOARD MANAGEMENT

80

Onboard management was found to be good overall. The computer-based Safety Management System (SMS) was deemed to be functioning and well implemented in general, with Permits to Work (PTW), risk assessments and procedures understood and followed. Onboard management was found to deal with accidents, near misses and deficiencies in an effective manner and regular safety committee meetings were carried out on board. The vessel's MLC certificate was valid with records of hours of rest (ILO) correct and up to date and maximum work hours not regularly exceeded. The PMS system was found to be kept up to date with no critical overdue work

orders. The Class-approved system-based Planned Maintenance System (PMS) was fully integrated with the SMS for ordering spares and general vessel management. The Port State Control (PSC) history was found to be very good with 0 deficiencies and 0 detentions in the 6 inspections conducted in the past three years. The vessel's flag is not targeted by any Memorandum of Understanding (MoU) or the USCG. Security access controls were deemed to be satisfactory with the vessel conforming to International Ship and Port Security (ISPS) standards. The Master and crew were prepared for the inspection and provided good cooperation with the majority of requested documents.

VESSEL CAPABILITIES AND CARGO SYSTEMS

80

Vessel capabilities and cargo systems were deemed to be in a good overall condition. Cargo holds 1, 2, 4, 5, 6 and 7 were entered for inspection. The inspected cargo holds were found to be free of structural defects as well as any significant corrosion and coating breakdown with only minor abrasions noted to the lower hoppers from operational wear and tear. Cargo hold fittings such as ladders, handrails pipe guards etc. were seen to have slight damage and bend on the ladder and platform in certain holds. Hold 01 vertical ladder was seen with a slight bent. Hold 02 protection bars from pipes were observed with a slight bent. Hold 05 platform from the vertical leader was observed with slightly bent and hold 05 protection bars for pipes were seen bent at certain places. The last cargo carried was Coal (Coking, Steam Coal), with the next intended cargo reported to be Grain (Wheat, Maize, Rye, Barley etc.). The cargo holds were free of signs of water ingress both from internal and external sources. Cargo monitoring systems such as bilges, temperature sensors, water ingress sensors etc. were reported to be fully operational and regularly tested. The vessel is fitted with Side rolling hatch covers, which were seen to be well-aligned

and closing correctly. Hatch covers were found to be free of structural defects and had only minor localised spot corrosion, not more than 5% of the surface area, mainly located on the interior sides, edges, wheels and cleats. Hatch cover operating systems were in full working order and were seen to be in good condition, free of corrosion and leakages. Hatch cover rubber seals and retaining channels were in good overall condition and free of temporary means of sealing such as foam or sealing tape. Hatch cover securing and hold open arrangements along with landing pads were seen to be in a good overall condition with no notable defects observed. Hatch coamings and longitudinal continuation brackets were found to be free of structural defects and had only minor localised spot corrosion, not more than 5% of the surface area, mainly located on the frames and edges. Compression bar/strips were seen to be in good condition with hatch coaming drain channels free of corrosion, scaling and debris and the hatch coaming non-return valves clear and operational. Stability calculations were seen to be carried out and the vessel holds a Document of Compliance (DOC) for the carriage of Dangerous Goods (DG).

NOTABLE ITEMS

Description	Estimated Cost [USD]
<p>Issue: Cargo Hold No.1 vertical ladder was observed with a slight bent, Hold No.2 pipe protection bars were observed with a slight bent, Hold No.5 platform from the vertical leader was observed with a slight bent and Hold No.5 protection bars for pipes were seen bent at certain places.</p>	<p>\$1000 - \$5000</p>
<p>Corrective Action: To plan and repair as considered necessary.</p>	



OPERATIONAL DATA

Operational Data Condition

Does the vessel have an Exhaust Gas Cleaning System (EGCS)? No

Total High Sulphur Fuel Oil (HSFO) capacity:	0 m ³
Total Very and Ultra Low Sulphur Fuel Oil (VLSFO and ULSFO) capacity:	2,441.5 m ³
Total Marine Gas Oil (MGO) and Diesel Oil (DO) capacity:	302.4 m ³

Does the vessel have any energy efficiency technologies installed? No

Engines Table

	Main Engine 1	Main Engine 2	Aux Engine 1	Aux Engine 2	Aux Engine 3	Aux Engine 4
Designer	MAN B&W	N/A	Yanmar	Yanmar	Yanmar	
Model	ME-C		6EY18ALV	6EY18ALV	6EY18ALV	
Mark/Series/Revision	8		7,579FXG	7,580FXG	7,581FXG	
Number of Cylinders	6		6	6	6	
Speed (RPM)	92		900	900	900	
Bore (mm)	600		180	180	180	
Stroke (mm)	2,400		280	280	280	
Specific Fuel Oil Consumption (SFOC) (g/kWhr) At 75% load for ME and 50% load for AEs, corrected to ISO conditions, as stated on Nox technical files	167		210.75	210.75	210.75	
Nox Tier	1		1	1	1	
Fuel Oil Consumption at full load (tonnes/day)	30.5		2.5	2.5	2.5	
Cylinder Oil Consumption (litres/day)	140					
System Oil Consumption (litres/day)	50		10	10	10	

Major Overhaul Interval (Hours)			12,000	12,000	12,000	
Running Hours since last overhaul (Hours)			11,953	9,461	9,449	

	Vessel Speed (knots)	Consumption (t/day)
Loaded Eco	12	23
Loaded Service	13.50	33
Ballast Eco	13	21
Ballast Service	14	28

Main Engine Maintenance

Component	Condition Based Monitoring?	Overhaul Interval
Cylinder Heads		16,000
Pistons		16,000
Bearings	Yes	
Cylinder Liners	Yes	

Main Engine No.1

Unit Running Hours

	1	2	3	4	5	6	7	8	9	10	11	12
Cylinder Heads	4,567	2,719	2,719	0	0	6,658						
Pistons	4,567	2,719	2,719	0	0	6,658						
Bearings	37,703	37,703	37,703	37,703	37,703	37,703						
Cylinder Liners	37,703	37,703	37,703	37,703	37,703	37,703						

Class Surveys

- Were all Class and Statutory certificates valid? Yes
- Is the vessel on the Extended Dry Docking (EDD) program? No
- Is the vessel on the Enhanced Survey Program (ESP)? Yes
- Does the vessel have an In Water Survey Class notation? Yes
- Is the vessel ice classed? No

Survey

Date Last Completed

Date Next Due

Survey	Date Last Completed	Date Next Due
Main / Special / Renewal	17-Jan-22	14-Mar-27
Intermediate	17-Feb-20	14-Mar-24
Annual	22-Jan-23	14-Mar-24
Bottom In Water		16-Jan-25
Bottom in dry dock	17-Jan-22	14-Mar-27

What was the location of the last out-of-water docking?

Shanhaiguan Shipbuilding Industry Co - China

Is the vessels last dry dock report provided and attached?

Yes

Has the vessel remained with the same flag since build?

Yes

Has the vessel remained with the same Class since build?

Yes

In total, how many of the following does the vessel have?: Conditions of Class, Recommendations of Class, Statutory Findings, Statutory Items, Conditions of Authority, Etc.

0

Does the vessel have any Class Memos, Observations or Additional Requirements?

Yes

Memorandum for owner and surveyor as follows: 1. The M/E power/speed was limited, the M/E power performance of the vessel as follows: Max continuous output(MCR) : 8,141 kw Engine speed at MCR : 85.6 rpm. 2.Two(2) sets of International Load Line Certificate were issued and kept on board the ship. The International Load Line Certificate corresponding to the summer free board 5,559 mm was in use and the International Load Line Certificate corresponding to the summer freeboard 7,206 mm was sealed in an envelope. 3.With effect from January 1,2,010, ships at berth in Europe Union ports for more than two(2) hours shall not use marine fuels with a sulphur content exceeding 0.1% by mass except that ships switch off all engines and use shore side electricity while at berth in ports. Please refer to Article 4b of EU Directive2,005/33/EC for details. 4.Periodic servicing of launching appliances of survival crafts and on-load release gear of lifeboats or rescue boats should be carried out in accordance with SOLAS Ch.III/Reg.20.11 at specific intervals. Next fiveyear servicing should be performed not later than January 14, 2,027. 5.The means of embarkation and disembarkation should be operationally tested with the specified maximum operational load in accordance with SOLAS Ch.II-1/Reg.3-9. Next date of Max. operational load test on accommodation ladder/winch is January 12, 2,027.

Please provide further details

The cost for the next out of water bottom survey or dry docking based on a far eastern shipyard and includes all survey and normal maintenance costs is approximately estimated at:

900,000

What was the status of the vessel at the time of inspection?

Loading

DESIGN AND CONSTRUCTION

Design and Construction Condition

Has the vessel been built to the standards and Rules of an IACS-member Class Society? Yes

Under what IACS Class society supervision was the vessel built?

CCS - China Classification Society

Did the vessel provide Ultrasonic Thickness Measurement (UTM) reports?

No, vessel less than 10 years old

Hull & Structure

Bridge & Communication

What features were seen on the bridge? Differential-GPS
Furuno

Engine Room & Firefighting

What features were seen in the engine room? Engine Power Limiter (EPL)
What is the new maximum power of the Main Engine as limited by the EPL? (kW) 8,141

as per relevant Class Memo

- Incinerator sludge burning system
- UMS Capabilities (regardless of Class notation)

HULL

Hull Condition

What sections of the hull were inspected?

Port side

Was the vessel free of any major structural damage or indentations?

Yes

Was the vessel free of any minor structural damage or indentations?

Yes

What was the level of Hull coating breakdown and corrosion?

Minor

Coating breakdown and corrosion was mainly located in the following areas:

along the shell plate, mostly on the aft part

The amount of surface area coating breakdown and corrosion was approximately:

5%

Type of coating breakdown and corrosion:

Localised

Spot

What was the condition of the hull markings?

Well painted and clearly legible

What level of marine fouling was seen?

None

Were fenders installed on the hull?

No

MOORING DECKS

Mooring Decks Condition

Were the decks free of any structural damage or deformations? Yes

What was the level of coating breakdown and corrosion observed on the decks?

Minor

Coating breakdown and corrosion was mainly located in the following areas:

observed on the weld seams

The amount of surface area coating breakdown and corrosion was approximately:

5%

Type of coating breakdown and corrosion:

Localised

Spot

What was the general condition of the deck fittings?

Good

Were fairleads and mooring rollers free to move when tested? Yes

Were all mooring machinery reported to be fully operational? Yes

What type of windlass(es) and winches were fitted?

Hydraulic

Were the windlass(es) and winches seen to be free of hydraulic oil leaks? Yes

Was the mooring machinery hydraulic pump unit (HPU) seen to be free from leaks? Yes

What was the condition of the mooring machinery?

Good

What amount of band brake lining was seen to be remaining?

Moderate/Adequate

What condition were the visible sections of the anchor chains seen to be in?

Good

What type of mooring lines did the vessel have?

Rope

What was the condition of the mooring ropes / wires?

Good

Were safe mooring practices observed? i.e. no overlapping turns on split drum, chafing of lines or unsafe leading.

No

certain mooring drums were seen with overlapping turns on split drums and certain mooring drums were seen with inadequate turns on split drums

Was the last brake test seen to be stencilled on the mooring winches?

Yes

Date of last test

02-Jun-23

What type of snap back warning signs/zones were posted?

Signs at the entrance to the mooring decks

Was the Bosun's / Foc'sle store available for inspection?

Yes

What was the condition of the bosun's store structure?

Structurally sound with no visible damage

What was the condition of the bosun's store coatings?

Coatings fully intact with no corrosion

Was the condition of the bosun's store housekeeping?

Neat and tidy with items secured

Were the bitter end release arrangements seen to be clear and unobstructed?

Yes

Was an 'emergency towing booklets/procedures' available near to the foc'sle?

Yes

WEATHER DECKS AND FITTINGS

Weather Decks and Fittings Condition

Were the decks free of any structural damage or deformations? Yes

What was the level of coating breakdown and corrosion observed on the decks?

Minor

Coating breakdown and corrosion was mainly located in the following areas:

cross deck sections

The amount of surface area coating breakdown and corrosion was approximately:

4%

Type of coating breakdown and corrosion:

Localised

Spot

What was the general condition of the deck fittings e.g handrails, brackets, vent heads, walkways, lighting etc.?

Good

Does the vessel have mooring winches fitted on the main deck? Yes

What was the condition of the mooring winches?

Good

Were deck equipment and pipework free of leakages? Yes

What was the condition of the accommodation ladders or gangways?

Good

Was the vessel fitted with a provision lifting appliance(s)? Yes

What was the condition of the provision lifting appliance(s)?

Good

Does the vessel carry any major spares on external decks e.g. propeller blades, anchor etc. No

BALLAST TANKS AND SYSTEMS

Ballast Tanks and Systems Condition

Were ballast tanks entered? No

Reason tanks were not entered:

Ballast tanks full or required for cargo operations

Were recent (last 12 months) ballast tank inspection photographs provided? Yes

Date photos were provided:

18-Dec-22

Were inspection reports or reports of the tanks condition provided? Yes

Were the tanks free of any structural damage or indentations? Yes

What was the level of Ballast Tank coating breakdown and corrosion?

Minor

Coating breakdown and corrosion was mainly located in the following areas:

edge of structural members, frames and plating.

The amount of surface area coating breakdown and corrosion was approximately:

5%

Type of coating breakdown and corrosion: Localised

Spot

What was the condition of ballast tank fittings (e.g. ladders, handrails, pipes & manhole seals)?

Good

Were the ballast tanks fitted with sacrificial anodes? Yes

Anode depletion:

10%

How much mud/sediment was seen inside the ballast tanks?

None

Were the tanks seen to be free from any signs of staining from oil, sewage or marine fouling?

Yes

Were ballast tank manhole covers seen to be in good condition?

Yes

Were the remote ballast control systems fully operational (e.g. valves, gauging etc)?

Yes

Were the ballast and/or anti-heeling pumps reported to be fully operational?

Yes

What condition were the ballast and/or anti-heeling pumps in?

Good

ACCOMODATION

Internal Accomodation Condition

Were accommodation spaces used for their assigned purposes? Yes

What was the condition of the flooring and wall coverings?

Good

What was the condition of the upholstery and furniture?

Good

What were the general levels of housekeeping and cleanliness?

Good

What was the level of hygiene of the sanitary facilities?

Good

Was all laundry equipment in good working order? Yes

Was the Hospital well equipped and ready for use? Yes

Were the drugs found to be controlled and secured with the associated drugs log kept up to date? Yes

What was the quality of accommodation outfitting?

Average quality of outfitting

Did the Air Handling Unit (AHU) maintain a comfortable temperature? Yes

What was the condition of the AHU?

Good

Galley Condition

What was the level of cleanliness in the Galley?

Clean

Was all galley equipment operational?

Yes

What was the general condition of galley equipment?

Good

Were the insides of Galley hoods clean?

Yes

What type of cold provisions stores does the vessel have?

Walk-in stores / Cold rooms

Were provisions stores well organised with no provisions stored directly on the deck?

Yes

Were provisions stores clean and hygienic?

Yes

Were provisions stores at the required temperatures?

Yes

Were provision stores temperatures recorded and records kept nearby?

Yes

Were provisions machinery, pipework and door seals free of frosting and deterioration?

Yes

Were lock-in alarms or handles in good working condition?

Yes

External Areas Condition

Was the external Superstructure / Accommodation Block found to be free from damages?

Yes

Were accommodation external doors found to be in good condition and providing an adequate seal?

Yes

What was the level of external accommodation superstructure coating breakdown and corrosion?

Minor

Coating breakdown and corrosion was mainly located in the following areas:

porthole edges and weld seams

The amount of surface area coating breakdown and corrosion was approximately:

3%

Type of coating breakdown and corrosion:

Localised

Spot

What was the general condition of external superstructure fittings?

Good

Crew Welfare

What is the average contract length for crew members?

Officers:

7 Months

Crew:

9 Months

Was Wi-Fi provided on-board?

Yes, Free, Limited

What is the approximate average internet speed?

Average (Able to access social media apps and websites with ease)

Is access provided to catering facilities or food at all times?

Yes

What Public Recreation equipment did the crew have access to?

- Free Weights
- Treadmill
- Table Tennis
- Games console
- Entertainment Library - Books, DVDs, Games, etc.
- Barbecue
- En-suite facilities for all crew members
- Fixed weight machine
- Cycling Machine
- Television
- Karaoke
- Musical Instruments
- Public Computer

What was the quality of crew recreation facilities?

Good

Are crew given time and resources to celebrate religious or cultural events (i.e. Christmas, Independence days etc.)?

Yes

What facilities were provided in crew cabins?

 Sofa Desk Ample storage

Does the vessel have any onboard training facilities?

Yes

Type of onboard training facilities:

 Videotel Seagull

Is there a crew suggestion policy in place?

 Yes

Does the crew have access to a bonded store?

Yes, minimal stock

Are the crew given additional periods of rest throughout the working week (e.g Sunday off)?

Yes

BRIDGE AND NAVIGATION EQUIPMENT

General Condition

Was all the bridge equipment reported to be fully operational? Yes

Was the bridge found to be clean and well maintained with good housekeeping? Yes

Were all required bridge equipment annual performance tests (e.g. VDR and AIS) completed in the last 12 months? Yes

Was the vessel fitted with a Voyage Data Recorder (VDR)? Yes

Type of VDR fitted: VDR

Was the VDR seen to be free from any unanticipated alarms? Yes

Were the VDR collection instructions posted and known to the Master? Yes

Was the vessels Bridge Navigation and Watch Alarm System (BNWAS) fully operational, and turned on when at sea? Yes

Normal time setting at sea 12 mins

Navigation Condition

	Primary	Secondary
What was the vessels primary & secondary means of navigation as listed on Form E?	ECDIS	ECDIS

Were the primary & secondary means of navigation found to be up to date? Yes

Latest update week

34

Does the vessel receive up to date weather information?

Yes

31-Aug-23

What type of weather updating service does the vessel use?

Other

Other type:

Ocean Route company, SPOS and weather fax

Was an in-date compass deviation card posted near to the helm?

Yes

Was a compass deviation log kept, up to date and free of any major deviations?

Yes

Were azimuth rings (bearing diopters) found to be available on the bridge?

Yes

Communication Condition

What GMDSS sea areas was the vessel licensed to cover?

A1

A2

A3

A4

Were the radio batteries seen to be in good condition?

Yes

Were the EPIRBs, SARTs and Emergency Hand Held VHF Batteries within their expiry dates?

Yes

Battery expiry dates

EPIRBs	01-Jan-26
SARTs	01-Jan-26
VHF	01-Jan-26

Was a valid GMDSS shore servicing certificate seen to be posted near to radio equipment?

Yes

Documentation Condition

Were berth to berth passage plans seen on-board?

Yes

Were passage plans signed by all navigating officers?

Yes

What format were nautical publications provided in?

Paper and Electronic

Were the Master's standing orders and night orders found to be signed by all navigating officers?

Yes

Was the bridge log book up to date and correctly filled in?

Yes

Was the GMDSS log book up-to-date and correctly filled in?

Yes

Date of last test

30-Aug-23

External Condition

Was the Monkey Island found to be in good, well maintained condition?

Yes

Were the main mast, aerials and antennas seen to be in good condition and free from damage?

Yes

Were bridge wing manoeuvring controls fitted?

No

Were bridge wing engine speed and compass repeaters seen to be in good working condition?

Yes

ENGINE ROOM AND MACHINERY

General Condition

What equipment was seen running?

- Auxiliary Engines
- Purifiers
- Pumps
- Air compressors

Was the engine room free of any significant defects, either reported by crew or observed?

- Yes

What was the general cleanliness of the Engine Room?

Clean

Were bilges and tank tops free of oil and water?

- Yes

Was housekeeping to a good overall standard?

- Yes

Was the vessel equipped with adequate critical spares as recommended by the ship manager Safety Management System (SMS)?

- No

few items are not on board as per critical spare parts list provided

Were spares neatly stowed and correctly secured?

- Yes

Were all sounding pipe self-closing devices in good working order and sounding pipes capped?

- Yes

Were recent copies of lube oil analysis reports provided for review?

- Yes

Were any caution (amber) or action (red) alerts seen on the lube oil analysis reports?

- No

Was the NOx Technical file kept up to date?

- Yes

Date of entry:

24-Aug-23

Were Chief Engineer Standing Orders clearly posted and signed by all engineers?

- Yes

Were all machinery special tools provided and in good condition?

- Yes

Main Engine Condition

Was the main engine in good working condition? Yes

What condition did the Main Engine appear to be in?

Fair

Please provide further details

oil stains and minor leaks were observed on cylinder heads and near fuel pumps at forward end of main engine.

Were Main Engine performance reports provided for review? Yes

Were the performance reports satisfactory? Yes

Was there any overdue maintenance on the Main Engine Turbochargers? No

Propulsion

What type of propulsion does the vessel have?

Fixed Pitch Propeller (FPP)

Were the Propulsion systems, including shafts, machinery and electric motors, if relevant, in good working condition? Yes

What type of thruster systems does the vessel have? None

Power Generation

How many Auxiliary Engines does the vessel have?

3

Were the auxiliary engines in good working condition? Yes

What condition did the Auxiliary Engines appear to be in?

Fair

Please provide further details

oil leakage was observed near Auxiliary engine No.1 Fuel filters

Were Auxiliary Engines performance reports provided for review?

Yes

Were the performance reports satisfactory?

Yes

Does the vessel have a shaft generator?

No

Does the vessel have a shaft motor (Power Take-In)?

No

Auxiliary Machinery

Does the vessel have an Auxiliary Boiler?

Yes

What type of boiler is fitted?

Steam

Was the boiler in good working condition?

Yes

What condition did the Boiler appear to be in?

Good

Were boiler safety valves in satisfactory condition?

Yes

Equipment	Fully operational?	Condition
Purifiers	Yes	Good
Pumps	Yes	Good
Coolers	Yes	Good
Air Compressors	Yes	Good
Fresh Water Generator	Yes	Good
Filters	Yes	Good
Fans	Yes	Good
Refrigeration Systems	Yes	Good

Was all engine room pipework free of leakages? No *evidence of hydraulic oil leakage around pipework related to hand operated hydraulic pumps on engine room bottom plates*

Was all pipework free of temporary repairs? Yes

Was all pipework free of corrosion or soft patches? Yes

What condition was pipework lagging in?	Stain
---	-------

Was the steering gear in good working condition? Yes

Was the steering gear free of leakages? Yes

Was the emergency steering communication equipment and gyro repeater working as required? Yes

Were emergency steering instructions posted nearby? Yes

Was the Engine workshop clean and tidy? Yes

ECR and Electrical

Was the Engine Control Room clean and tidy? Yes

Was the Engine Control and Alarm system free of any serious alarms? Yes

Does the vessel have an Unmanned Machinery Space (UMS) notation? Yes

Does the machinery space operate in UMS mode? Yes

Were all Electrical distribution systems in good working condition? Yes

Were Main Switchboard Insulation readings adequate? Yes

Were distribution and switchboard panels protected with approved rubber matting? Yes

Was the Emergency Generator tested during the inspection? Yes

Was the Emergency Generator in working order? Yes

Were Emergency Generator Starting instructions clearly posted? Yes

What was the condition of the Emergency Generator?

Good

Was the "18 hour" fuel level marked on the emergency generator fuel tank? Yes

FIRE FIGHTING EQUIPMENT AND SYSTEMS

Fire and Safety Appliances Condition

Was the vessel free of fire hazards? Yes

Was all fire and safety equipment regularly serviced? Yes

Date of last service

26-Aug-23

Were all relevant Fire and Safety instructions correctly posted? Yes

What was the vessels Fixed fire detection systems?

	Engine Room	Cargo Holds	Accommodation
<input checked="" type="checkbox"/> Flame			
<input checked="" type="checkbox"/> Smoke			
<input checked="" type="checkbox"/> Heat			
<input checked="" type="checkbox"/> Smoke & Heat (Combined)			

Was the fire detection system reportedly fully operational? Yes

Was the fire detection system free of alarms or signs of tampering? Yes

What is the vessels Fixed firefighting systems?

Engine Room	Cargo Holds	Accomodation
<input checked="" type="checkbox"/> CO2	<input checked="" type="checkbox"/> CO2	<input checked="" type="checkbox"/> Water Mist
<input checked="" type="checkbox"/> Foam	<input checked="" type="checkbox"/> Deck Foam	<input checked="" type="checkbox"/> Galley CO2
<input checked="" type="checkbox"/> Water Spray	<input checked="" type="checkbox"/> Water Spray	<input checked="" type="checkbox"/> Wet Chemical
<input checked="" type="checkbox"/> None	<input checked="" type="checkbox"/> None	<input checked="" type="checkbox"/> None

Were all fixed fire fighting systems in good working condition? Yes

Were clear operating instructions posted for the fixed firefighting systems? Yes

Was the fixed firefighting system release protected against unauthorised operation? Yes

Was the main fire pump working? Yes

Was the emergency fire pump working? Yes

Was a fire pump tested during the inspection? Yes

Did the fire pump maintain adequate pressure? Yes

Were the main and emergency fire pumps in good condition and free of leakages? Yes

What was the condition of the fire main and ancillaries such as pipework hydrants and valves?

Good

Does the vessel have a fire control station? Yes

Were all portable equipment in place as per the fire plan? Yes

Were all fire extinguishers in good condition? Yes

Were the firefighting outfits and associated equipment in good condition? Yes

Were the International Shore Connections on board? Yes

Location:

Near accommodation entrance

Was the BA equipment fully charged in good condition? Yes

Was the Quick Closing Valve system in good working order? Yes

Were fire doors in good condition and effectively closing? Yes

Were fire doors free of unauthorised "hold-open" arrangements? Yes

Were all ventilation dampers remote closing positions well labelled and in good working order? Yes

Were all remote machinery shutdown systems well labelled and in good working order? Yes

LIFESAVING APPLIANCES

Lifesaving Appliances Condition

Were all Lifesaving Appliances regularly serviced? Yes

Date of last service:

26-Aug-23

How many lifeboats is the vessel equipped with?

1

What type of lifeboat is the vessel fitted with?

Free-fall

What was the external condition of the lifeboat(s)?

Good

What was the internal condition of the lifeboat(s)?

Good

Were Lifeboat Engines able to be tested? Yes

Were lifeboat engines in good working order? Yes

What was the condition of the rescue boat?

Good

How many life rafts does the vessel have?

5

What was the condition of the life rafts?

Good

Were Liferaft Hydrostatic Release Units (HRU) in date and correctly rigged? Yes

What was the condition of the Davits and lowering arrangements for the lifeboat(s), rescue boat and liferafts?

Good

What Date is the next Davit wire due for change?

11-Jan-27

Were legible launching/recovery instructions posted near to survival craft?

Yes

Was evidence of regular maintenance, service and inspection of the launching appliances sighted and evident?

Yes

What was the date of the last abandon ship drill?

13-Aug-23

Were all lifejackets, immersion suits, EEBDs and other lifesaving ancillary equipment in good condition and ready for use?

Yes

Were Man Overboard Buoy (MOB) smoke and light signals in date?

Yes

Were the embarkation ladders in a good, well maintained condition?

Yes

Were pyrotechnics and line throwing apparatus available, stored in an appropriate container and within their expiry dates?

Yes

SAFE WORKING ENVIRONMENT

Safe Working Environment Condition

Were any unsafe practices observed during the inspection? No

Did the vessel provide a safe working environment? Yes

Were all hazard markings clear? Yes

Were external walkways adequately coated with anti-slip paint and free of trip hazards? Yes

Are all hazardous substances including safely managed and stored with relevant Material Safety Data Sheets (MSDS)? Yes

Is Personal Protective Equipment (PPE) provided and worn by crew? No

not all crew were seen to be wearing the required PPE when on the open decks

Are 'Enclosed Space Entry' procedures implemented? Yes

Is an effective Permit To Work (PTW) process implemented? Yes

Date of last PTW:

24-Aug-23

Is an effective Risk Assessment (RA) process in place? Yes

Was evidence of the annual and 5-yearly inspections of both fixed and portable lifting equipment and appliances sighted? Yes

Are main and emergency exits clearly identified and unobstructed? Yes

Are sufficient portable oxygen and gas detection meters provided and regularly calibrated? Yes

Date of last calibration:

14-Nov-22

What is the working language of the vessel?

English

Are standing orders, procedures, instructions and manufacturers' manuals written in a language which can be understood by the crew?

Yes

Are all IMO signs correctly placed, and compliant with IMO requirements?

Yes

Is the vessel equipped with an approved SOLAS training manual?

Yes

Were the pilot ladders and boarding arrangements in a good, safe condition?

Yes

Are regular drills conducted on board?

Yes

Last drill date

13-Aug-23

Last drill type

Abandon ship, Fire fighting, Oil spill and Rescue boat

POLLUTION CONTROL

General Condition

Was Pollution Control well implemented within the on board Safety Management System (SMS)? Yes

Is the vessel free of pollution hazards?

Yes, with no hazards

Does the vessel have a Class approved Inventory of Hazardous Materials (IHM)? Yes

The vessel holds a Class approved Inventory of Hazardous Material (IHM)

Oil - Marpol Annex I

Is an Oily Water Separator (OWS) fitted? Yes

Was the OWS reportedly operational? Yes

What was the condition of the OWS?

Good

Was the OWS Tested? Yes

Means of testing

Simulated

Was the 15ppm meter calibrated? Yes

Date of calibration

12-Aug-21

Was the Bilge Overboard valve secured against unauthorised opening with adequate signage and warnings posted? Yes

Means of securing

Sealed

Locked

Was the oily water treatment system including valves and pipework free of any signs of tampering, bypass, or modifications? Yes

Was the SOPEP locker or box well stocked? Yes

What was the condition of the SOPEP equipment?

Good

Was a list of SOPEP equipment posted and accurate? Yes

Was the Oil Record Book (ORB) up to date and correctly filled in? Yes

Date of last entry

29-Aug-23

Category of last entry

C

Were previous bunkering checklists correctly filled out? Yes

Date of last bunkering

03-Jul-23

Were bunker samples correctly stored? Yes

Does the vessel have a Ballast Water Treatment System (BWTS) fitted? Yes

Ballast Water Treatment System

Manufacturer:

Qingdao Headway Technology Co. Ltd

Type:

Electrolysis

What regulation is listed on the Ballast Water Management Certificate?

D-2

Type of BWTS approval:

IMO approval

Was the BWTS operational? Yes

What was the condition of the BWTS?

Good

Was the Ballast Record Book up to date and correctly filled in?

Yes

Date of last entry

09-Aug-23

Is the Vessel General Permit (VGP) compliant?

Yes

Due to the use of an EAL or the airseal arrangements in place for the stern tube, the vessel is considered VGP compliant in this regard for trade to the USA

How is the vessel VGP Compliant? *Environmentally Acceptable Lubricant

Stern Tube Airseal

Sewage - Marpol Annex IV

Was a Sewage Treatment Plant fitted?

Yes

Was the Sewage Treatment Plant operational?

Yes

What was the condition of the Sewage Treatment Plant?

Good

Does the vessel have a sewage holding tank?

Yes

What was the condition of the Sewage Holding Tank?

Good

Garbage - Marpol Annex V

How was the condition of Garbage segregation?

Good

Were Garbage containers of approved, non-combustible type?

Yes

Was the Garbage Record Book (GRB) up to date and correctly filled in?

Yes

Date of last entry

17-Aug-23

Category of last entry

C

Air - Marpol Annex VI

How does the vessel comply with IMO 2,020 regulations?

Use of Very Low Sulphur Fuel Oils (VLSFO), MGO, DO etc.

Does the vessel use Ozone Depleting Substances (ODS) as Refrigerant Gas?

No

Was an Incinerator fitted?

Yes

Was the Incinerator operational?

Yes

What was the condition of the Incinerator?

Good

Does the vessel have an Emission Control Area (ECA) change-over log?

Yes

Date of last entry

21-Nov-22

EEXI

Does the vessel have an EEDI score assigned at build?

Yes

What is the EEDI score?

3.69

Does the vessel have any energy efficiency technologies installed?

No

Is the vessel ice classed?

No

Main Engine(s)

Specific Fuel Oil Consumption (SFOC) (g/kWhr):

167

Auxiliary Engines

Specific Fuel Oil Consumption (SFOC) (g/kWhr):

210.75

Does the vessel have a shaft motor (Power Take-In)?

 No

What is the expiry date of the International Air Pollution Prevention (IAPP) certificate?

14-Mar-27

ONBOARD MANAGEMENT

Onboard Management Condition

Does the vessel have a functioning Safety Management System (SMS)? Yes

How was the SMS Implemented?

Software / Electronic System

Were the officers familiar with, and allowed easy access to, the SMS? Yes

Was the SMS well implemented on board, with Permits to Work, Risk Assessments and Safety procedures understood and followed? Yes

Is the SMS system regularly reviewed by the Master? Yes

Date of last review

14-May-23

Does the vessel management deal with accidents, near-misses and deficiencies in an effective manner? Yes

Are regular safety committee and management meetings carried out on board? Yes

Does the vessel have a valid MLC certificate? Yes

Were Hours of Rest (ILO) records correct and up to date? Yes

Last updated

29-Aug-23

Are hours of maximum permissible work regularly exceeded? No

Is an effective Planned Maintenance System (PMS) implemented and kept up to date? Yes

What type of Planned Maintenance System (PMS) does the vessel have?	Class-approved system
Name of PMS	Bassnet

Was the PMS a fully integrated type system? (i.e. has integration with the SMS, spares ordering and is accessible by shore side management) Yes

Were there any critical overdue PMS work orders? No

Port State Control (PSC) inspection history

No. of Inspections in Past three years:	6
No. of Deficiencies in Past three years:	0
No. of Detentions in Past three years:	0

Is the vessel flag targeted by Port State Authorities? No

Is an effective system of security access control, conforming to ISPS standards, in place upon boarding the vessel? Yes

Type of access control	On gangway by duty crew
------------------------	-------------------------

Do the Master and Chief Engineer have an effective hand over procedures? Yes

Are random or specific drug and alcohol testing carried out? Yes

Tests Carried out by	Onboard by Master	External Company
----------------------	-------------------	------------------

Were the Master and crew prepared for the Inspection? Yes

What level of cooperation was provided by the crew and Master?

Good

Were documents provided as requested?

Majority of documents provided

What was the overall impression of the general management of the vessel?

Well managed

VESSEL CAPABILITIES AND CARGO SYSTEMS - BULK

Vessel Capabilities and Cargo Systems - Bulk Condition

Cargo hold	Capacity (m ³)	Uniform deck load limit (t/m ²)	Steel Coil Capacity By: Total weight (mt)
Cargo Hold No.1	12,495.2		
Cargo Hold No.2	14,928.9		
Cargo Hold No.3	14,465.7		
Cargo Hold No.4	12,827.8		
Cargo Hold No.5	13,945.8		
Cargo Hold No.6	13,889.4		
Cargo Hold No.7	14,275.5		
Total	96,828.3		0

How many cargo holds does the vessel have?

7

Were the cargo holds able to be entered and inspected?

Yes

Which holds were entered

1, 2, 4, 5, 6 and 7. Cargo hold 03 was under loading operation.

Were recent vessel cargo hold inspection photographs provided? No

Were any cargo hold inspection reports or condition information provided? No

Were cargo holds structural members found to be free from damage (e.g. side plating, tank top and framing)? Yes

Were the cargo hold fittings such as ladders, hand rails and pipe guards etc. found to be free from damage? No *slight damage and bend of ladder and platform in certain holds.*

What was the level of cargo hold coating breakdown and corrosion?

None

What was the last cargo carried?

Coal (Coking, Steam Coal)

What is the next intended cargo to be carried?

Grain (Wheat, Maize, Rye, Barley etc)

Were all cargo monitoring systems (e.g. bilges, temperatures, water ingress etc.) fully operational and regularly tested? Yes

Were cargo hold bilges dry, clean and clear of debris or cargo? Yes

Were the cargo holds free from signs of water ingress? Yes

Were the cargo holds free from signs of previous and/or current internal leaks (e.g. from manholes or adjacent tanks etc)? Yes

What is the method of cargo hold ventilation?

Natural

Can any cargo holds be ballasted? Yes

No.4

Hatch Covers Condition

What type of hatch covers are fitted?

Side rolling

What was the make of the Hatch covers?

TTS

Were the hatch covers found to be correctly aligned? Yes

Were the hatch cover found to be free from structural damage? Yes

What level of coating breakdown and corrosion was seen on the hatch covers?

Minor

Coating breakdown and corrosion was mainly located in the following areas:

interior sides and edges

The amount of surface area coating breakdown and corrosion was approximately:

3%

Type of coating breakdown and corrosion: Localised

Spot

Were the hatch cover operating systems found to be fully operational? Yes

What was the condition of the hatch cover operating system, free from corrosion, leakage etc.?

Good

What was the condition of the hatch cover rubber seals/gaskets and retaining channels?

Good

Were the hatch covers free from temporary means of sealing such as expanding foam or sealing tape? Yes

What was the condition of hatch cover securing arrangements?

Good

What was the condition of hatch cover hold-open arrangements?

Good

What was the condition of the hatch cover landing pads?

Good

Hatch Coamings Condition

Were the hatch coamings found to be free from structural damage, paying particular attention to hatch coaming longitudinal stays? Yes

What was the level of hatch coaming coating breakdown and corrosion?	Minor
Coating breakdown and corrosion was mainly located in the following areas:	frames and edges
The amount of surface area coating breakdown and corrosion was approximately:	2%

Type of coating breakdown and corrosion: Localised Spot

Were the compression bars/strips seen to be in good condition? Yes

Were the hatch coaming drain channels seen to be free from corrosion, scaling or debris? Yes

Were hatch coaming non-return valves found to be clear and fully operational? Yes

Documentation and Additional Features

Does the vessel have a Document of Compliance (DOC) for the carriage of dangerous goods? Yes

Does the vessel have a Certificate of Authority to carry grain? Yes

Was there an approved Cargo Loading Manual on board? Yes

Is the vessel certified to carry heavy cargoes? Yes

Was there an approved stability booklet on board? Yes

Did the vessel use a Class-approved computer based loading/stability software? Yes

Name of software	Shipmanager-88
------------------	----------------

Were previous and current stability calculations seen to be carried out? Yes

Is the vessel fitted with equipment for the carriage of additional cargoes (e.g. Log stanchions, lashing points etc.)? No

Does the vessel carry her own cargo grabs? No

CARGO LIFTING APPLIANCES

Cargo Lifting Appliances Condition